

SREEROSH SYMPHONY

WORK PROGRESS PHOTOS
APRIL 2022



PILE CAP PCC WORK



PILE CAP SHUTTERING & STEEL WORK



RCC WORK OF PILE CAP



RETAINING WALL SHUTTERING & STEEL WORK



RCC WORK OF RETAINING WALL



BASEMENT FLOOR COLUMN & PLINTH BEAM WORKS

