




SREEROSH LAURELS

PROGRESS REPORT APRIL 2025




PROJECT AT GLANCE



■ RCC
 ■ CEILING PLASTERING
 ■ MASONRY
 ■ WALL CHASING
 ■ WALL PLASTERING
 ■ PLUMBING
 ■ WATERPROOFING


FLOORING STATUS



PROGRESS PHOTOS




East & South Elevation



Passage & staircase flooring



Granite works



Toilet daddoing



Painting works



Joinery work



Electrical work



Fire fighting work



Plumbing work



Terrace waterproofing



Wooden Joinery

THANK YOU

