



SREEROSH ICON
PROGRESS REPORT JULY 2026



PILING WORK PROGRESS



PILE CAP WORK PROGRESS



BALANCE TO COMPLETE	Excavation	Pile chipping
COMPLETED		

PROGRESS PHOTOS



BARBENDING WORKS



BARBENDING WORKS



PILE CHIPPING WORK



PILE CHIPPING WORK

THANK YOU